


NOTES: 1. THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH WOOD ENVIRONMENT & INFRASTRUCTURE REPORT NO. NX14001B "MYRA FALLS TAILINGS STORAGE FACILITIES 2018 DAM SAFETY INSPECTION REPORT", DATED MARCH 2019. 2. SURFACE SHOWN IS A COMPILATION OF 2015 LIDAR, JANUARY 2018 UNMANNED AERIAL VEHICLE (UAV), NOVEMBER 2018 UAV AND AS-BUILT SURVEY DATA FROM 2015, 2016, 2017 AND 2018 CONSTRUCTION. 3. CONTOUR INTERVAL: 10 m.													Client:				DATUM: MINE		PROJECT: MYRA FALLS RE-DISTURBED AREAS 2018		PROJECT NO.: NX14001B	
															PROJECTION: MINE		REVISION NO. A					
															DRAWN BY: K.L.		TITLE: SITE PLAN AS OF DECEMBER 31, 2018		DATE: MARCH 2019			
															REVIEWED BY: D.H.G.				FIGURE NO.: 2			
															SCALE: 1:10000							
				31		03		2019		ISSUED FOR 2018 ANNUAL RECLAMATION REPORT		NP		-								
				REV		D		M		Y		ISSUE / REVISION DESCRIPTION		ENG.		APPR.						

\\bny-151\bay-se-min\PROJECTS\Open\NX14001B\3 - Annual Env Rep Review\Drawings\Fig.dwg - Fig. - Mar. 26, 2019 3:36pm - kweilin