



2016 Environmental Technical Review Committee Stakeholder Meeting

November 23, 2016


Agenda Item 2.

- Overview and Status of Activities
 - Mine and Ownership Status
 - Site Activities: Reclamation and Water Management


Site Activities: Reclamation and Water Management

- Areas that could be part of future mine activity are in “Care and Maintenance”
 - All obligations of the Mine Permit and Effluent Permit being followed
 - Underground mine ventilation and pumping systems being maintained
 - All surfaces water management systems being maintained
- Areas where mining activity is complete and would not be required for any future mining are being reclaimed as described in the closure plan
 - 242 exploration adit
 - 4-South portals and raw coal pad
 - 2-South and 3-South open pit areas
 - 2-North Mine 6-Mains pumping system removed

2-North Mine



7-South



Reclamation: 242 Exploration Adit



Reclamation: 4-South Portals and Coal Stockpile Pad



Reclamation: 1-South Sump



Reclamation: 2-South Pit



Reclamation: 3-South North Dump



Reclamation: 3-South Pit Highwall



Reclamation: 3-South Pit Outlet Channel

